. Littingal Curp

9155419

## IRREGULARITY REPORT

Type: Complaint	Pollution X	Unpermitted D	ischarge [
District 1 Count Location of Discharge: thence into the Houston	River y 008 Basin 10 West of Lubrizol from t Ship Channel.	Date of Inspection heir skimming ponds	5/15/70 into Patrick's Bayou
Nature of Discharge: SI water.	kimming pond overflow -	discharged waste-le	bricant products plus
How and When Discovere Manager of Lubrizol; the	d: Received a phone cal overflow was discovered	ll from Mr. Phil Kro I at 7:30 am, May 15	g, Assistant Ceneral
Name and Address of Co	mplainant: N/A		ر المراجعة المراجعة المراجعة المراجعة ال
Name and Address of Di	scharger: Lubrizol Co	orporation, P.O. Box	158, Deer Park, Tex. 77536
Description and Narrat	ion:	•	
On May 15, 1970, Mr. P. report an oil spill from Houston Ship Channel. M Assistant Production Man General Manager of tabrinto Patrick's Bayou.	their skimming ponds in r. C. Masterson and I co ager, Mr. Al Lee, Plant	nto Patrick's Bayou Ontacted Mr. P. Krug Technologist, and M	, thence into the 3, Mr. Scott Barra, Mr. W. P. Martens,
Approximately 500 gallon into Patrick's Bayou. To color and it covered an containing the oily substact two points, vaccum tradoing a sufficient job.	he waste-lubricant disco area of about 40 yards. ance adequately. No of	blored the Bayou to Booms were placed I had escaped over t	a chocolate brown in several places the final boom.
A request was made and g in clean-up procedures,			
Clean-up procedures were retaining and recovering		l did all they could	i in containing,
ta "	INIT FIGUR SCAY	ines	Was Bown
	6.1. U	Inra	Old Will State
Approved The State	Signature///	6 Geta Dave	May 15, 1970